



W.E.S.S.

WELDING EQUIPMENT SALES & SERVICE

WELDING SAFETY

Service and Maintain your Powered Air Purifying Respiratory System properly to ensure its optimum performance and your personal protection at all times.

The team at W.E.S.S. are trained and accredited by 3M/Speedglas to Sell, Service & Repair Powered Air Purifying Respiratory Systems. Bring your system back to us for regular complete servicing to original condition.

- Full System Inspection & Testing: Air flow, Battery & Lens
- Replace all filters (if required)
- Replace all cover lenses
- Fully Sanitise all areas of the PAPR
- Test and Tag battery charger to AS/NZS 3760
- Charge battery

Note: Replacement with Original Parts

Please be aware particle and gas filters cannot be cleaned they must be replaced to maintain air quality. Please refer to the recommended change frequency table on the back of this page.

Contact WESS to schedule service. Call (08) 8243 2200 or email service@wess.com.au

3M / Speedglas Recommended Change Frequencies



Part Number	Description	Change Frequency
3M™ Adflo™ Powered Air Purifying Respirator (PAPR)		
836010	PRE-FILTER ADFLO PK=5	ONCE-TWICE A WEEK
837010	FILTER PARTICLE PSL ADFLO	ONCE A MONTH
3M™ Speedglas™ G5-01		
198505	SWEATBAND G5-01 PK=5	ONCE A MONTH
526000	LENS COVER OUTER STD G5-01 PK=10	ONCE-TWICE A WEEK
527000	LENS COVER OUTER HC G5-01 PK=10	ONCE A FORTNIGHT
528025	LENS COVER INNER G5-01 PK=5	ONCE A MONTH
613000	VISOR PLATE ANTI FOG G5-01 PK=5	EVERY 2-4 WEEKS DEPENDING ON USE
614000	FACE SEAL G5-01	ONCE EVERY TWO MONTHS
3M™ Speedglas™ 9100 MP Air		
168505	SWEATBAND 9100 MP AIR PK=5	ONCE A MONTH
523000	VISOR PLATE 9100 FX & MP PK=5	EVERY 2-4 WEEKS DEPENDING ON USE
523001	VISOR PLATE ANTI-FOG 9100 FX & MP PK=5	EVERY 2-4 WEEKS DEPENDING ON USE
526000	LENS COVER OUTER STD 9100 PK=10	ONCE-TWICE A WEEK
527000	LENS COVER OUTER HC 9100 PK=10	ONCE A FORTNIGHT
528025	COVER LENS INNER 9100XX/XXI PK=5	ONCE A MONTH
534200	FACE SEAL 9100 MP AIR	ONCE EVERY TWO MONTHS
3M™ Speedglas™ 9100 FX & 9100 FX Air		
169505	SWEATBAND 9100 FX & 9100 FX AIR PK=5	ONCE A MONTH
523000	VISOR PLATE 9100 FX & MP PK=5	EVERY 2-4 WEEKS DEPENDING ON USE
523001	VISOR PLATE ANTI-FOG 9100 FX & MP PK=5	EVERY 2-4 WEEKS DEPENDING ON USE
526000	LENS COVER OUTER STD 9100 PK=10	ONCE-TWICE A WEEK
527000	LENS COVER OUTER HC 9100 PK=10	ONCE A FORTNIGHT
528025	COVER LENS INNER 9100XX/XXI PK=5	ONCE A MONTH
534000	FACE SEAL 9100 FX AIR	ONCE EVERY TWO MONTHS
3M™ Speedglas™ 9100, 9100 Air & 9100 QR		
169505	SWEATBAND 9100 & 9100 AIR PK=5	ONCE A MONTH
526000	LENS COVER OUTER STD 9100 PK=10	ONCE-TWICE A WEEK
527000	LENS COVER OUTER HC 9100 PK=10	ONCE A FORTNIGHT
528025	COVER LENS INNER 9100XX/XXI PK=5	ONCE A MONTH
534100	FACE SEAL 9100 AIR	ONCE EVERY TWO MONTHS
167505	SWEATBAND 9100 QR PK=5	ONCE A MONTH
3M™ Speedglas™ 9002NC		
168505	SWEATBAND 9002 PK=5	ONCE A MONTH
428010	COVER LENS INNER 9002NC PK=5	ONCE A MONTH
426000	COVER LENS OUTER STD 9002 PK=10	ONCE-TWICE A WEEK
3M™ Speedglas™ 100V		
168505	SWEATBAND 100 PK=5	ONCE A MONTH
428000	COVER LENS INNER 100 PK=5	ONCE A MONTH
776000	COVER LENS OUTER STD 100 PK=10	ONCE-TWICE A WEEK